






	Evering is through energy efficiency	Energy Code Technical Support Program
GENERAL AIR BARRIER CRIT	ERIA	
		24




























		tion
-	1	FRAMING INSPECTION
	Ceiling/attic	 The air barrier in any dropped ceiling/soffit shall be aligned with the insulation and any gaps in the air barrier shall be sealed.
	Walls	The junction of the foundation and sill plate shall be sealed. The junction of the top plate and the top of exterior walls shall be sealed. Knee walls shall be sealed. Walls are framed to allow the corner to be insulated or continuous insulation is/will be installed.
	Windows, skylights and doors	 The space between window/door jambs and framing, and skylights and framing shall be sealed.
	Rim joists	Rim joists shall include the air barrier.
	Floors (including above garage and cantilevered floors)	The air barrier shall be installed at any exposed edge of insulation.
	Crawl space walls	 Exposed earth in unvented crawl spaces shall be covered with a Class I vapor retarder with overlapping joints taped.
	Garage separation	Air sealing shall be provided between the garage and conditioned spaces.
	Shower/tub on exterior wall	 Exterior walls adjacent to showers and tubs shall be insulated The air barrier installed at exterior walls adjacent showers and tubs shall separate them from the showers and tubs.
	Electrical/phone box on exterior walls	The air barrier shall be installed behind electrical or communication boxes or air-sealed boxes shall be installed.
	Concealed sprinklers	 When required to be sealed, concealed fire sprinklers shall only be sealed in a manner that is recommended by the manufacturer. Caulking or other adhesive sealants shall not be used to fill voids between fire sprinkler cover plates and walls or ceilings.





Courtesy of the Department of Energy's Building America Solution Center (<u>http://basc.energy.gov</u>)

